

**BEFORE THE ARKANSAS HVAC/R LICENSING BOARD
IN THE MATTER OF JARRETT L. BROWN, RESPONDENT
LICENSE NO. 0003817 EXP. 3-31-2024
CASE NO. KB12042024A**

FINDINGS OF FACT, CONCLUSION OF LAW AND ORDER

A hearing on the above-referenced matter was held before the Arkansas HVAC/R Board ("Board") at 10:00 a.m. on November 12, 2025, located at 900 West Capitol Ave., Suite 400, Little Rock, AR 72201. Jarrett Brown ("Respondent") did appear personally by zoom. Arkansas Department of Labor and Licensing Counsel Lacie Kirchner appeared on behalf of the Board.

Finding proper notice had been given Respondent, the Board, from all the evidence presented, makes the following Findings of Fact, Conclusions of Law, and Order.

FINDINGS OF FACT

1. Jarrett L. Brown ("Respondent") did and at all times relevant, hold an expired HVAC/R Class A license, license number 0003817.
2. Respondent is the owner of Bricoleur HVAC and Repair, located in Walnut Ridge, Arkansas.
3. On or about December 4, 2024, Inspector Kerry Baker inspected the Hawkins residence in Leachville, Arkansas. He found the respondent had performed work without a valid license. Which constituted a violation of Ark. Code Ann. § 17-33-301. On or about May 29, 2025, Inspector Woodard noted three (3) violations of the IFCG Code (International Fuel Gas Code).
4. On or about December 10, 2024, Inspector Baker performed a complete inspection of the residence's attic space and noted thirty-two (32) violations of the IMC Code (International Mechanical Code).
5. On or about December 4, 2024, December 18, 2024, and January 24, 2025. Respondent affirmed that he would have a licensed contractor return to the property and make the corrections.

6. On or about February 10, 2025, Respondent informed Baker he would not have someone return to the property due to a payment issue with the homeowner.
7. The Board determined that based on the evidence presented, Respondent was not responsible at this time for violations relevant to the incomplete installation relating to the fire suppression system.

CONCLUSIONS OF LAW

1. Respondent's actions, as set forth above in Findings of Fact 1, constitute a violation of Ark. Code Ann. §17-33-301 that Respondent failed to obtain valid licensure prior to engaging in work.
2. Respondent's actions, as set forth above in Findings of Fact 4, constitute two (2) violations of IMC 304.1 -Installation to manufacturer's instructions - Not found with unit.
3. Respondent's actions, as set forth above in Findings of Fact 4, constitute a violation of IMC 312.1 -Heat load required.
4. Respondent's actions, as set forth above in Findings of Fact 4, constitute a violation of IMC 301.17 -Rodent proofing.
5. Respondent's actions, as set forth above in Findings of Fact 4, constitute twelve (12) violations of IMC 603.9 -Duct Sealing.
6. Respondent's actions, as set forth above in Findings of Fact 4, constitute ten (10) violations of IMC 603.4 -Metallic Duct Construction.
7. Respondent's actions, as set forth above in Findings of Fact 4, constitute a violation of IMC 603.2 -Duct sizing in accordance with ACCA manual D.
8. Respondent's actions, as set forth above in Findings of Fact 4, constitute five (5) violations of IMC 603.18 -Balancing Damper Required.

