

**BEFORE THE ARKANSAS HVAC/R LICENSING BOARD
IN THE MATTER OF DALLAS LANDRY, RESPONDENT
NON-LICENSED
CASE NO. KB109162024A**

FINDINGS OF FACT, CONCLUSION OF LAW AND ORDER

A hearing on the above-referenced matter was held before the Arkansas HVAC/R Board ("Board") at 10:00 a.m. on January 14, 2026, located at 900 West Capitol Ave., Suite 400, Little Rock, AR 72201. Dallas Landry ("Respondent") did not appear personally or by zoom.

Finding proper notice had been given Respondent, the Board, from all the evidence presented, makes the following Findings of Fact, Conclusions of Law, and Order.

FINDINGS OF FACT

1. Dallas Landry ("Respondent") did and at all times relevant, was not licensed by the HVAC/R Board.
2. Respondent is the owner of Comfort Kings, located in Pocahontas, Arkansas.
3. On or about September 16, 2024, Inspector Kerry Baker inspected the Ivy residence in Powhatan, Arkansas. He found the respondent had performed work without a valid license. Which constituted a violation of Ark. Code Ann. § 17-33-301.
4. On or about September 16, 2024, Inspector Baker performed a complete inspection of the residence's and noted twenty-one (21) violations of the IMC Code (International Mechanical Code).
5. On or about September 19, 2024, Inspector Baker spoke with Landry and explained the licensing requirements and made the option available, he could hire a licensed HVAC/R mechanic to come out and repair the work. Respondent affirmed that he would have a licensed contractor return to the property and make the corrections.

6. On or about October 29, 2024, Inspector Baker performed a re-inspection and found no corrections had been made.

CONCLUSIONS OF LAW


1. Respondent's actions, as set forth above in Findings of Fact 3, constitute a violation of Ark. Code Ann. §17-33-301 that Respondent failed to obtain valid licensure prior to engaging in work.
2. Respondent's actions, as set forth above in Findings of Fact 4, constitute multiple violation(s) of IMC 301.10 – Electrical – eight separate (8) areas noted.
3. Respondent's actions, as set forth above in Findings of Fact 4, constitute multiple violation(s) of IMC 304.1 - Manufacturer's Instructions – six (6) separate violations noted.
4. Respondent's actions, as set forth above in Findings of Fact 4, constitute multiple violation(s) of IMC 307.2.2 – Drainpipe materials and sizes - three (3) separate violations noted.
5. Respondent's actions, as set forth above in Findings of Fact 4, constitute a violation of IMC 312.1 – Load calculation
6. Respondent's actions, as set forth above in Findings of Fact 4, constitute multiple violation(s) of IMC 1109.21.2 - Refrigerant pipe enclosure – three (3) violations noted.

ORDER

1. Respondent is hereby ordered to pay a civil money penalty in the amount of four thousand, eight hundred dollars (\$4,800.00) within sixty (60) days of the date of this Order.
2. Any further violations of law or rules of the Board or failure on the part of the Respondent to comply with the terms and conditions of this Order may result in additional sanctions.

Pursuant to the Arkansas Administrative Procedure Act, Ark. Code Ann. §25-15-212, Respondent may petition for judicial review of this decision by filing a petition in the Circuit Court in the County in which he resides or does business or in the Circuit Court of Pulaski County within thirty (30) days after service of this Order.

HEATING, VENTILLATION, AIR CONDITIONING and
REFRIGERATION LICENSING BOARD, DEPARTMENT
OF LABOR AND LICENSING,
STATE OF ARKANSAS

By: 
Alan Dean, Chairman

Date: 1-22-2026