

**BEFORE THE ARKANSAS BOARD OF LICENSURE FOR
PROFESSIONAL ENGINEERS AND PROFESSIONAL SURVEYORS**

Case #2009-05, in the matter of David Jorgensen:

COMPLAINT

The Arkansas Board of Licensure for Professional Engineers and Professional Surveyors (hereinafter "the Board") registered a complaint on January 20, 2009, charging David L. Jorgensen (AR-PS #1118, hereinafter "Jorgensen") with failing to place identifier caps on field monumentation, in violation of Section 3.2.C.2.a of the Arkansas Minimum Standards for Property Boundary Surveys & Plats. Failure to adhere to these standards is a violation of Article 14.A.5 of the Rules of the Board.

FINDINGS OF FACT

1. Jorgensen's consulting firm contracted for the design, field staking, and layout of a subdivision in Fayetteville, Arkansas.
2. The Complainant was retained to do a lot survey in an adjacent subdivision. When he went out to do the field work, he found the pins set for the lots in Jorgensen's subdivision did not have identifier caps, and he filed a complaint.
3. Jorgensen's written response did not dispute the basic facts of the complaint, but provided evidence he was not paid for the work.


CONCLUSIONS OF LAW

Upon review of the evidence in its possession, the Board finds Jorgensen's actions as described in the Findings of Fact do not constitute a violation of the statutes or rules governing the Arkansas Board of Licensure for Professional Engineers and Professional Surveyors.

ORDER

Based on these findings, the complaint against Jorgensen is dismissed without further action by the Board.

SO ORDERED this 15th day of September, 2009




Frank Vozel, President

CERTIFICATE OF SERVICE

I, Steve W. Haralson, Executive Director of the Arkansas State Board of Registration for Professional Engineers and Land Surveyors, do hereby certify that I have served a copy of the foregoing order by mailing a copy of the same by first class mail on this 30th day of September, 2009, to:

Mr. David L. Jorgensen, PS
Jorgensen & Assoc Consult Engineers
124 W Sunbridge Dr Ste 5
Fayetteville, AR 72703-1870

A handwritten signature in black ink, appearing to read "S. Haralson", written over a horizontal line.

Steve W. Haralson
Executive Director